Pace Analytical Services, LLC
8 East Tower Circle
Ormond Beach, FL 32174
(386)672-5668

February 23, 2022

Glenn Walker
Brunswick County Water Systems
PO Box 249
Bolivia, NC 28422

RE: Project: 1,4-DX-522 (Weekly)
Pace Project No.: 35696276

Dear Glenn Walker:

Enclosed are the analytical results for sample(s) received by the laboratory on February 11, 2022. The results relate only to the samples included in this report. Results reported herein conform to the applicable TNI/NELAC Standards and the laboratory's Quality Manual, where applicable, unless otherwise noted in the body of the report.

The test results provided in this final report were generated by each of the following laboratories within the Pace Network:

- Pace Analytical Services - Ormond Beach

If you have any questions concerning this report, please feel free to contact me.

Sincerely,

Bill White
bill.white@pacelabs.com
(386) 672-5668
Project Manager

Enclosures

cc: Billy Benton, BRUNSWICK COUNTY PUBLIC UTILITIES

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, LLC.

Pace Analytical Services, LLC
8 East Tower Circle
Ormond Beach, FL 32174
(386)672-5668

CERTIFICATIONS

Project: 1,4-DX-522 (Weekly)
Pace Project No.: 35696276

Pace Analytical Services Ormond Beach
8 East Tower Circle, Ormond Beach, FL 32174
Alaska DEC- CS/UST/LUST
Alabama Certification #: 41320
Colorado Certification: FL NELAC Reciprocity
Connecticut Certification #: PH-0216
Delaware Certification: FL NELAC Reciprocity
Florida Certification #: E83079
Georgia Certification #: 955
Guam Certification: FL NELAC Reciprocity
Hawaii Certification: FL NELAC Reciprocity
Illinois Certification #: 200068
Indiana Certification: FL NELAC Reciprocity
Kansas Certification #: E-10383
Kentucky Certification #: 90050
Louisiana Certification #: FL NELAC Reciprocity
Louisiana Environmental Certificate #: 05007
Maine Certification #: FL01264
Maryland Certification: #346
Michigan Certification #: 9911
Mississippi Certification: FL NELAC Reciprocity
Missouri Certification #: 236
Montana Certification #: Cert 0074
Nebraska Certification: NE-OS-28-14
New Hampshire Certification #: 2958
New Jersey Certification #: FL022
New York Certification #: 11608
North Carolina Environmental Certificate #: 667
North Carolina Certification #: 12710
North Dakota Certification #: R-216
Ohio DEP 87780
Oklahoma Certification #: D9947
Pennsylvania Certification #: 68-00547
Puerto Rico Certification #: FL01264
South Carolina Certification: #96042001
Tennessee Certification #: TN02974
Texas Certification: FL NELAC Reciprocity
US Virgin Islands Certification: FL NELAC Reciprocity
Virginia Environmental Certification #: 460165
West Virginia Certification #: 9962C
Wisconsin Certification #: 399079670
Wyoming (EPA Region 8): FL NELAC Reciprocity

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, LLC.

Pace Analytical Services, LLC
8 East Tower Circle
Ormond Beach, FL 32174
(386)672-5668

SAMPLE SUMMARY

Project: 1,4-DX-522 (Weekly)
Pace Project No.: 35696276

Lab ID	Sample ID	Matrix	Date Collected	Date Received
35696276001	**021022-SO1**	Water	02/10/22 08:45	02/11/22 11:15
35696276002	**021022-EO1**	Drinking Water	02/10/22 08:45	02/11/22 11:15

REPORT OF LABORATORY ANALYSIS

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, LLC.

Pace Analytical Services, LLC
8 East Tower Circle
Ormond Beach, FL 32174
(386)672-5668

SAMPLE ANALYTE COUNT

Project: 1,4-DX-522 (Weekly)
Pace Project No.: 35696276

Lab ID	Sample ID	Method	Analysts	Analytes Reported	Laboratory
35696276001	**021022-SO1**	EPA 522	PFG	2	PASI-O
35696276002	**021022-EO1**	EPA 522	PFG	2	PASI-O

PASI-O = Pace Analytical Services - Ormond Beach

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, LLC.

Pace Analytical Services, LLC
8 East Tower Circle
Ormond Beach, FL 32174
(386)672-5668

ANALYTICAL RESULTS

Project: 1,4-DX-522 (Weekly)
Pace Project No.: 35696276

Sample: 021022-SO1 **Lab ID: 35696276001** Collected: 02/10/22 08:45 Received: 02/11/22 11:15 Matrix: Water

Parameters	Results	Units	PQL	MDL	DF	Prepared	Analyzed	CAS No.	Qual
522 MSS 1,4 Dioxane	Analytical Method: EPA 522 Preparation Method: EPA 522								
	Pace Analytical Services - Ormond Beach								
1,4-Dioxane (p-Dioxane)	**1.6**	ug/L	0.20	0.12	1	02/18/22 23:15	02/21/22 14:50	123-91-1	
Surrogates									
1,4-Dioxane-d8 (S)	88	%	70-130		1	02/18/22 23:15	02/21/22 14:50		

Sample: 021022-EO1 **Lab ID: 35696276002** Collected: 02/10/22 08:45 Received: 02/11/22 11:15 Matrix: Drinking Water

Parameters	Results	Units	PQL	MDL	DF	Prepared	Analyzed	CAS No.	Qual
522 MSS 1,4 Dioxane	Analytical Method: EPA 522 Preparation Method: EPA 522								
	Pace Analytical Services - Ormond Beach								
1,4-Dioxane (p-Dioxane)	**2.7**	ug/L	0.20	0.12	1	02/18/22 23:15	02/21/22 15:06	123-91-1	
Surrogates									
1,4-Dioxane-d8 (S)	79	%	70-130		1	02/18/22 23:15	02/21/22 15:06		

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, LLC.

Pace Analytical Services, LLC
8 East Tower Circle
Ormond Beach, FL 32174
(386)672-5668

QUALITY CONTROL DATA

Project: 1,4-DX-522 (Weekly)
Pace Project No.: 35696276

QC Batch: 801523
QC Batch Method: EPA 522
Analysis Method: EPA 522
Analysis Description: 522 MSS 1,4 Dioxane
Laboratory: Pace Analytical Services - Ormond Beach
Associated Lab Samples: 35696276001, 35696276002

METHOD BLANK: 4401665 Matrix: Water
Associated Lab Samples: 35696276001, 35696276002

Parameter	Units	Blank Result	Reporting Limit	MDL	Analyzed	Qualifiers
1,4-Dioxane (p-Dioxane)	ug/L	0.12 U	0.20	0.12	02/21/22 12:42	
1,4-Dioxane-d8 (S)	%	91	70-130		02/21/22 12:42	

LABORATORY CONTROL SAMPLE: 4401666

Parameter	Units	Spike Conc.	LCS Result	LCS % Rec	% Rec Limits	Qualifiers
1,4-Dioxane (p-Dioxane)	ug/L	20	18.4	92	70-130	
1,4-Dioxane-d8 (S)	%			92	70-130	

LABORATORY CONTROL SAMPLE: 4401667

Parameter	Units	Spike Conc.	LCS Result	LCS % Rec	% Rec Limits	Qualifiers
1,4-Dioxane (p-Dioxane)	ug/L	0.2	0.18 I	91	50-150	
1,4-Dioxane-d8 (S)	%			91	70-130	

MATRIX SPIKE SAMPLE: 4402063

Parameter	Units	60392747001 Result	Spike Conc.	MS Result	MS % Rec	% Rec Limits	Qualifiers
1,4-Dioxane (p-Dioxane)	ug/L	133	19.9	148	77	70-130	
1,4-Dioxane-d8 (S)	%				97	70-130	

SAMPLE DUPLICATE: 4402064

Parameter	Units	60392747002 Result	Dup Result	RPD	Max RPD	Qualifiers
1,4-Dioxane (p-Dioxane)	ug/L	16.6	16.4	1	20	
1,4-Dioxane-d8 (S)	%	89	88			

Results presented on this page are in the units indicated by the "Units" column except where an alternate unit is presented to the right of the result.

REPORT OF LABORATORY ANALYSIS

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, LLC.

Pace Analytical Services, LLC
8 East Tower Circle
Ormond Beach, FL 32174
(386)672-5668

QUALIFIERS

Project: 1,4-DX-522 (Weekly)
Pace Project No.: 35696276

DEFINITIONS

DF - Dilution Factor, if reported, represents the factor applied to the reported data due to dilution of the sample aliquot.

ND - Not Detected at or above adjusted reporting limit.

TNTC - Too Numerous To Count

MDL - Adjusted Method Detection Limit.

PQL - Practical Quantitation Limit.

RL - Reporting Limit - The lowest concentration value that meets project requirements for quantitative data with known precision and bias for a specific analyte in a specific matrix.

S - Surrogate

1,2-Diphenylhydrazine decomposes to and cannot be separated from Azobenzene using Method 8270. The result for each analyte is a combined concentration.

Consistent with EPA guidelines, unrounded data are displayed and have been used to calculate % recovery and RPD values.

LCS(D) - Laboratory Control Sample (Duplicate)

MS(D) - Matrix Spike (Duplicate)

DUP - Sample Duplicate

RPD - Relative Percent Difference

NC - Not Calculable.

SG - Silica Gel - Clean-Up

U - Indicates the compound was analyzed for, but not detected.

N-Nitrosodiphenylamine decomposes and cannot be separated from Diphenylamine using Method 8270. The result reported for each analyte is a combined concentration.

Reported results are not rounded until the final step prior to reporting. Therefore, calculated parameters that are typically reported as "Total" may vary slightly from the sum of the reported component parameters.

Pace Analytical is TNI accredited. Contact your Pace PM for the current list of accredited analytes.

TNI - The NELAC Institute.

ANALYTE QUALIFIERS

I	The reported value is between the laboratory method detection limit and the laboratory practical quantitation limit.
U	Compound was analyzed for but not detected.

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, LLC.

Pace Analytical Services, LLC
8 East Tower Circle
Ormond Beach, FL 32174
(386)672-5668

QUALITY CONTROL DATA CROSS REFERENCE TABLE

Project: 1,4-DX-522 (Weekly)
Pace Project No.: 35696276

Lab ID	Sample ID	QC Batch Method	QC Batch	Analytical Method	Analytical Batch
35696276001	**021022-SO1**	EPA 522	801523	EPA 522	801871
35696276002	**021022-EO1**	EPA 522	801523	EPA 522	801871

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, LLC.

WO# : 35696276

35696276

CHAIN-OF-CUSTODY / Analytical Request Document

The Chain-of-Custody is a LEGAL DOCUMENT. All relevant fields must be completed accurately.

Page : 1 Of 1

Section A
Required Client Information:

Company:	Brunswick County Water Systems
Address:	PO Box 249
	Bolivia, NC 28422
Email To:	Glenn Walker
Phone:	910-371-3490 Fax:
Requested Due Date:	W007

Section B
Required Project Information:

Report To:	Glenn Walker
Copy To:	
Purchase Order #:	
Project Name:	1,4-Dx-522 (Weekly)
Project #:	

Section C
Invoice Information:

Attention:	Accounts Payable
Company Name:	See Section A
Address:	
Pace Quote:	
Pace Project Manager:	Lisa Harvey
Pace Profile #:	9551-1 (SO1) , -2 (EO1)

Regulatory Agency
NC
State / Location
NC

SAMPLE ID
One Character per box.
(A-Z, 0-9 / , -)
Sample Ids must be unique

MATRIX	CODE
Drinking Water	DW
Water	WT
Waste Water	WW
Product	P
Soil/Solid	SL
Oil	OL
Wipe	WP
Air	AR
Other	OT
Tissue	TS

Requested Analysis Filtered (Y/N)

ITEM #	SAMPLE ID	MATRIX CODE (see valid codes to left)	SAMPLE TYPE (G=GRAB C=COMP)	COLLECTED START DATE	COLLECTED START TIME	COLLECTED END DATE	COLLECTED END TIME	SAMPLE TEMP AT COLLECTION	# OF CONTAINERS	Unpreserved	H2SO4	HNO3	HCl	NaOH	Na2S2O3	Methanol	Sodium sulfite and sodium bisulfate	Analyses Test Y/N	522 - 1,4 - Dioxane	522 - 1,4 - Dioxane	Residual Chlorine (Y/N)	
1	021022-SO1	WT	G	2/10/2022	0845AM	2/10/2022	0845AM		1								1		1			line 1
2	021022-EO1	DW	G	2/10/2022	0845AM	2/10/2022	0845AM		1								1			1		line 2
3																						
4																						
5																						
6																						

ADDITIONAL COMMENTS	RELINQUISHED BY / AFFILIATION	DATE	TIME	ACCEPTED BY / AFFILIATION	DATE	TIME	SAMPLE CONDITIONS			
		2/10/2022		Mdtacy	2/11/22	1115	0.1	Y	N	Y

SAMPLER NAME AND SIGNATURE		TEMP in C	Received on Ice (Y/N)	Custody Sealed Cooler	Samples Intact (Y/N)
PRINT Name of SAMPLER:	BILLY BENTON				
SIGNATURE of SAMPLER:	2/10/2022				

SO1 is Raw Water (WT)

EO1 is Potable DWTR (DW)

Pace

Sample Condition Upon Receipt Form (SCUR)

Project #
Project Manager:
Client:

WO# : 35696276
PM: WBW Due Date: 02/23/22
CLIENT: BRUNCOWS

Date and Initials of person:
Examining contents: [illegible]
Label: [illegible]
Deliver: [illegible]
pH: _____

Thermometer Used: T-394 Date: 2-11-22 Time: 11:45 Initials: LDF

State of Origin: _____ ☐ For WV projects, all containers verified to ≤6 °C

Cooler #1 Temp.°C	0.1 (Visual)	0.0 (Correction Factor)	0.1 (Actual)	☐ Samples on ice, cooling process has begun
Cooler #2 Temp.°C	_____ (Visual)	_____ (Correction Factor)	_____ (Actual)	☐ Samples on ice, cooling process has begun
Cooler #3 Temp.°C	_____ (Visual)	_____ (Correction Factor)	_____ (Actual)	☐ Samples on ice, cooling process has begun
Cooler #4 Temp.°C	_____ (Visual)	_____ (Correction Factor)	_____ (Actual)	☐ Samples on ice, cooling process has begun
Cooler #5 Temp.°C	_____ (Visual)	_____ (Correction Factor)	_____ (Actual)	☐ Samples on ice, cooling process has begun
Cooler #6 Temp.°C	_____ (Visual)	_____ (Correction Factor)	_____ (Actual)	☐ Samples on ice, cooling process has begun

Recheck for OOT °C _____ **(Visual)** _____ **(Correction Factor)** _____ **(Actual) Time:** _____ **Initials:** _____

Courier: ☐ Fed Ex ☐ UPS ☐ USPS ☐ Client ☐ Commercial ☐ Pace ☐ Other _____

Shipping Method: ☐ First Overnight ☐ Priority Overnight ☐ Standard Overnight ☐ Ground ☐ International Priority
☐ Other _____

Billing: ☐ Recipient ☐ Sender ☐ Third Party ☐ Credit Card ☐ Unknown

Tracking # _____

Custody Seal on Cooler/Box Present: ☐ Yes ☑ No **Seals intact:** ☐ Yes ☐ No **Ice:** Wet Blue Melted None

Packing Material: ☑ Bubble Wrap ☐ Bubble Bags ☐ None ☐ Other _____

Samples shorted to lab (If Yes, complete) Shorted Date: _____ Shorted Time: _____ Qty: _____

		Comments:
Chain of Custody Present	☑ Yes ☐ No ☐ N/A	
Chain of Custody Filled Out	☐ Yes ☑ No ☐ N/A	
Relinquished Signature & Sampler Name COC	☐ Yes ☑ No ☐ N/A	* NO RELINQUISHED SIGNATURE
Samples Arrived within Hold Time	☑ Yes ☐ No ☐ N/A	
Rush TAT requested on COC	☐ Yes ☑ No ☐ N/A	
Sufficient Volume	☑ Yes ☐ No ☐ N/A	
Correct Containers Used	☑ Yes ☐ No ☐ N/A	
Containers Intact	☑ Yes ☐ No ☐ N/A	
Sample Labels match COC (sample IDs & date/time of collection)	☑ Yes ☐ No ☐ N/A	
All containers needing acid/base preservation have been checked.	☐ Yes ☐ No ☑ N/A	Preservation Information: Preservative: _____ Lot #/Trace #: _____ Date: _____ Time: _____ Initials: _____
All Containers needing preservation are found to be in compliance with EPA recommendation: Exceptions: Vials, Microbiology, O&G, PFAS	☐ Yes ☐ No ☑ N/A	
Headspace in VOA Vials? (>6mm):	☐ Yes ☐ No ☑ N/A	
Trip Blank Present:	☐ Yes ☐ No ☑ N/A	

Comments/ Resolution (use back for additional comments): _____